

CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY
SECURITY INFORMATION

INFORMATION REPORT

CD NO.

DATE DISTR. 15 December 1952

NO. OF PAGES 3

NO. OF ENCLS.
(LISTED BELOW)

PLACE
ACQUIRED

SUPPLE
REPORT

THIS DOCUMENT CONTAINS INFORMATION AFFECTING THE NATIONAL DEFENSE OF THE UNITED STATES, WITHIN THE MEANING OF TITLE 18, SECTIONS 793 AND 794, OF THE U.S. CODE, AS AMENDED. ITS TRANSMISSION OR REVELATION OF ITS CONTENTS TO OR RECEIPT BY AN UNAUTHORIZED PERSON IS PROHIBITED BY LAW. THE REPRODUCTION OF THIS FORM IS PROHIBITED.

50X1-HUM

50X1-HUM

1.

Dr. Matzke was in charge of the development laboratory and Augustine directed the studio construction and outfitting. The line potential varied between 200 and 230 volts while the frequency fluctuated from 47 to 55 cycles. adapting the available tubes, coils, etc, to the given conditions was a time-consuming job. Each of the four studios are to have four separate circuits: (1) TV; (2) tone; (3) signal; (4) power supply. There were four technicians and two draftsmen working in this office.

Studio 1, the smallest, was 80% finished and the other three had no electric installations at all. The two-hour daily programs televised motion pictures and stills. The subjects were usually political, with an occasional

CLASSIFICATION SECRET/CONTROL - U.S. OFFICIALS ONLY

[illegible]

SECRET/CONTROL - U.S. OFFICIALS ONLY

-2-

sprinkling of sports events. Broadcast was good but reception was below average. The programs were broadcast to City Hall (Berlin) on 300 mega Hz. There they were demodulated, remodulated and broadcast on 99.8 mega Hz. The tone was on a frequency 6.5 Hz lower. This is in the region of the police band, which causes much interference. The City Hall installation was made by Sachsenwerk-Radeberg. The antenna was constructed by Oberspreewerk.

Equipment and Personnel

2. The Central Laboratory at Adlershof is situated on land once occupied by the Reichs Luftwaffe. The building, three stories high with a basement, had about 60 rooms. It was guarded by dogs and men. The direction sender tower for transmitting to the City Hall was about 150 meters from the building. The equipment was good but there seemed to be a continuous shortage of materials and instruments. This was partly due to the complicated system of getting supplies. Copper and iron were particularly short. Iconoscopes were brought from Telefunken. The tubes that were available were of good quality. There was a good library which contained many German and English technical journals. In general, the technical men were competent. The following sections were under the direction of the men indicated:

Cameras - Heffmann

Impulse generators - Richter

Scanning - Siegel

50X1-HUM

Measuring Instruments - Jandt

Miniature tubes - Lindner

High Frequency - Sohr

Inter-room signals - Einsporn

Tone engineer - Bresov

Working Conditions

3. Everybody in the laboratory was carefully watched [redacted] Whenever a mishap occurred [redacted] all afraid of being falsely accused. Once there was a small fire which resulted from the explosion of a lamp bulb. The intense investigation that followed would have been justified had a murder been committed. Engineers have a pride in doing their work well and want to see things function. A "slow up" in work is hardly possible since the tempo of following a "plan" is necessarily very slow. [redacted]

50X1-HUM

50X1-HUM

50X1-HUM

Comments

4. [redacted]

The Technische Hoch-

SECRET/CONTROL - U.S. OFFICIALS ONLY

SECRET/CONTROL - U.S. OFFICIALS ONLY

-3-

schule has been largely repaired and rebuilt. [redacted]

[redacted] the equipment was good
and [redacted] the attendance was large. Apparently the academic
standards have not been lowered, for it is reported that many
peasant sons, encouraged to attend institutions of higher
learning, fail in their studies largely because of poor pre-
technical school preparation. [redacted]

50X1-HUM

50X1-HUM

SECRET/CONTROL - U.S. OFFICIALS ONLY